



Bid Notice Abstract

Request for Quotation (RFQ)

Reference Number 5907633
Procuring Entity BUREAU OF THE TREASURY
Title PREVENTIVE MAINTENANCE SERVICES OF TWO (2) UNITS GENERATOR SETS (1125/800 KVA) OF THE AYUNTAMIEN TO BUILDING
Area of Delivery Metro Manila

Solicitation Number:	2018-12-0509 FMD	Status	Pending
Trade Agreement:	Implementing Rules and Regulations		
Procurement Mode:	Negotiated Procurement - Small Value Procurement (Sec. 53.9)	Associated Components	1
Classification:	Goods	Bid Supplements	0
Category:	General Repair and Maintenance Services	Document Request List	0
Approved Budget for the Contract:	PHP 500,000.00	Date Published	13/12/2018
Delivery Period:	1 Year/s	Last Updated / Time	12/12/2018 11:14 AM
Client Agency:		Closing Date / Time	18/12/2018 12:00 PM
Contact Person:	Mr. Clarence Bolante Bunan Administrative Officer III Ayuntamiento Building, Cabildo St., cor. A. Soriano Intramuros, Manila Metro Manila Philippines 1002 63-2-6632206 63-2-5247008 cbbunan@treasury.gov.ph		

Description

PREVENTIVE MAINTENANCE SERVICES OF TWO (2) UNITS GENERATOR SETS (1125/800 KVA) OF THE AYUNTAMIEN TO BUILDING

BRIEF DESCRIPTION:

Preventive Maintenance Services for the generator sets greatly reduces the risk that an internal or ancillary component malfunction will cause the generator to produce insufficient power. It is intended to detect normal life-cycle deterioration of components within the system and replace those components before they fail.

DURATION OF CONTRACT

One (1) year

SCOPE OF WORK AND SERVICES

A. Exhaust System - with generator set operating, inspect the entire exhaust system including the exhaust manifold, muffler and exhaust pipe. Check for leaks at all connections, welds, gasket and joints, and make sure that the exhaust pipes are not heating surrounding areas excessively. Repair any leaks immediately.

B. Fuel System - With the generator set operating, inspect the fuel supply lines, return lines, filters and fittings for cracks or abrasions. Make sure that all lines are not rubbing against anything that could cause eventual breakage. Repair any leak or alter line routing to eliminate immediately.

C. DC Electrical Systems - check the terminals on the starting batteries fro clean and tight connections. Loose or corroded connections create resistance which can hinder starting.

D. Engine - monitor fluid levels, oil pressure and coolant temperature frequently. Most engine problems give an early warning. Look and listen for changes in engine performance, sound, or appearance that will indicate that service of repair is needed. Be alert for misfires, vibration, excessive exhaust smoke, and loss of power or increase in oil or fuel consumption.

OTHER RESPONSIBILITIES OF THE SUPPLIER/CONTRACTOR

A. Must have ten (10) years existence in the business.

B. The Contractor shall submit the following requirements:

*DTI/SEC registration certificate

*Mayor's Permit

*PhilGEPS Registration Certificate

RESERVATION CLAUSE

The BTr reserves the right to reject documents which do not comply with the requirements, waive any formalities of documents or consider any submission of documents as substantial compliance reject any and all bids; declare a failure of bidding, annul the bidding process, or not to award the contract, without thereby incurring any liability to the affected bidder or bidders or if the funds/allotment for the program/project/activity has been withheld or reduced through no fault of the BTr.

The BTr assumes no responsibility whatsoever to compensate or indemnify bidders for any expenses incurred in the preparation of the bid.

Line Items

Item No.	Product/Service Name	Description	Quantity	UOM	Budget (PHP)
1	PREVENTIVE MAINTENANCE SERVICES OF TWO (2) UNITS G	PREVENTIVE MAINTENANCE SERVICES OF TWO (2) UNITS GENERATOR SETS (1125/800 KVA) OF THE AYUNTAMIENTO BUILDING	1	Lot	500,000.00

Created by Mr. Clarence Bolante Bunan

Date Created 12/12/2018

The PhilGEPS team is not responsible for any typographical errors or misinformation presented in the system. PhilGEPS only displays information provided for by its clients, and any queries regarding the postings should be directed to the contact person/s of the concerned party.