

Bid Notice Abstract

Request for Quotation (RFQ)

Reference Number 5907041

Procuring Entity BUREAU OF THE TREASURY

Title PREVENTIVE MAINTENANCE SERVICES FOR FM200 FIRE SUPPRESSION SYSTEM FOR THE

AYUNTAMIENTO BUILDING

Area of Delivery Metro Manila

Solicitation Number:	2018-12-0503 FMD	Status	Pending
Trade Agreement:	Implementing Rules and Regulations		
Procurement Mode:	Negotiated Procurement - Small Value Procurement (Sec. 53.9)	Associated Components	1
Classification:	Goods - General Support Services	Bid Supplements	0
Category:	General Repair and Maintenance Services		
Approved Budget for the Contract:	PHP 500,000.00	Document Request List	0
Delivery Period:	1 Year/s		
Client Agency:		Date Published	13/12/2018
Contact Person:	Mr. Clarence Bolante Bunan Administrative Officer III		
	Ayuntamiento Building, Cabildo St., cor. A. Sorian Intramuros, Manila Manila	Last Updated / Time	12/12/2018 09:09 AM
	Metro Manila Philippines 1002 63-2-6632206 63-2-5247008 cbbunan@treasury.gov.ph	Closing Date / Time	18/12/2018 12:00 PM

Description

PREVENTIVE MAINTENANCE SERVICES FOR FM200 FIRE SUPPRESSION SYSTEM FOR THE AYUNTAMIENTO BUILDING

BRIEF DESCRIPTION:

Preventive Maintenance Services for sup[ply of manpower, test equipment and technical expertise of FM200 Fire Suppression System for the Ayuntamiento Building

DURATION OF CONTRACT:

One (1) Year

SCOPE OF WORK AND SERVICES:

A. Storage Racks and Cylinder Assembly

- *The storage rack is intact. Wall mounting bolts and other hardware has not been removed or tampered with.
- *The cylinder is free from evidence of corrosion.
- *The cylinder valves are free from mechanical damage.
- *The cylinder straps and the outlet fittings are connected to the pipping are intact.
- *The cylinder storage pressure reading.

B. Detection and Actuation System

*The detectors are free from foreign materials.

*The Supervisory features of the system in satisfactory condition.

C. Electrical Components

- *The control panel is intact, has not been removed or tampered with.
- *The battery reading
- *The manual release station is intact or has pulled down
- *The horn and strobe light are intact
- *The fire alarm bell is intact
- *The abort station is intact
- *The control panel buttons are operational
- *The wires in the control panel are properly

D. Piping and Nozzle

- *The piping is free from evidence of corrosion
- *The orifices of the nozzles are clear and unobstructed
- *The nozzles are in proper position

E. Ausxiliary Equipment

*All auxiliary components such as pressure switches, door closures, dampers and air handling shutdown are in proper operating condition.

F. Others

*Warning signs of the system are properly posted.

OTHER RESPONSIBILITIES OF THE SUPPLIER/CONTRACTOR

- A. Must have ten (10) years existence in the business.
- B. The Contractor shall submit submit the following requirements:
- *DTI/SEC registration certificate
- *Mayor's Permit
- *PhilGEPS Registration Certificate

RESERVATION CLAUSE

The BTr reserves the right to reject documents which do not comply with the requirements, waive any formalities of documents or consider any submission of documents as substantial compliance reject any and all bids; declare a failure of bidding, annul the bidding process, or not to award the contract, without thereby incurring any liability to the affected bidder or bidders or if the funds/allotment for the program/project/activity has been withheld or reduced through no fault of the BTr.

The BTr assumes no responsibility whatsoever to compensate or indemnify bidders for any expenses incurred in the preparation of the bid.

Created by Mr. Clarence Bolante Bunan

Date Created 12/12/2018

The PhilGEPS team is not responsible for any typographical errors or misinformation presented in the system. PhilGEPS only displays information provided for by its clients, and any queries regarding the postings should be directed to the contact person/s of the concerned party.

© 2004,2004,2004,2004,2004-2018 DBM Procurement Service. All rights reserved.,DBM Procurement Service. All rights reserved.

Help | Contact Us | Sitemap